

APPENDIX B

Systems Control
A Division of M. J. Electric, Inc.
Docket No. 99900712/83-01

NOTICE OF NONCONFORMANCE

Based on the results of an NRC inspection conducted on July 26-29, 1983, it appears that certain of your activities were not conducted in accordance with NRC requirements as indicated below:

- A. Systems Control's letters of corrective action dated September 4 and 15, and October 28, 1982, committed to effecting a QA Manual revision, developing a new procedure, and conducting training as it relates to the new procedure.

Contrary to the above, Systems Control did not implement their committed corrective actions.

- B. Systems Control's letters of corrective action dated May 16 and July 9, 1980, committed to reinstruction for welders and welding inspectors and to an intensified welder monitoring and weld inspection program.

Contrary to the above, it is apparent that Systems Control did not effectively maintain the committed corrective action as evidenced by numerous defective welds identified in Class 1E auxiliary relay cabinets provided to CP&L's Shearon Harris Nuclear Power Plant.