

POST OFFICE BOX 2951 * BEAUMONT, TEXAS 77704

AREA CODE 409 838 - 6631

February 13, 1984 RBG-17,006 File Nos. G9.5, G9.25.1.1

Mr. John T. Collins, Regional Administrator U. S. Nuclear Regulatory Commission Region IV, Office of Inspection and Enforcement 611 Ryan Plaza Drive, Suite 1000 Allington, Texas 76011

Dear Mr. Collins:

River Bend Station Unit 1 Docket No. 50-458 Interim Report/DR-160

Gulf States Utilities Company has not completed its investigation of DR-160 concerning transformer cable lead lugs supplied by Gould Brown-Boveri. An interim or final status report will be provided by April 23, 1984.

Sincerely,

J. E. Booker

J. E. Booker

Manager-Engineering, Nuclear Fuels & Licensing River Bend Nuclear Group

JEB/PJD/kt

cc: Director of Inspection & Enforcement U. S. Nuclear Regulatory Commission Washington, D. C. 20555

NRC Resident Inspector-Site

8402220395 840213 PDR ADOCK 05000458 S PDR