Carolina Power & Light Company ATLANTA, SEORGIA AND SOMEON PROPERTY AND ASSESSMENT

USNEC PERIOR I

HARTSVILLE, SOUTH CAROLINA 29550 CT 4 All: 22 H. B. ROBINSON STEAM ELECTRIC PLANT

SEP 2 9 1983

Robinson File No: 13510C

Serial: RSEP/83-1247

Mr. James P. O'Reilly Regional Administrator U. S. Nuclear Regulatory Commission Region II 101 Marietta Street, N. W., Suite 3100 Atlanta, Georgia 30303

> H. B. ROBINSON STEAM ELECTRIC PLANT, UNIT NO. 2 DOCKET NO. 50-261/ LICENSE NO. DPR-23 PROMPT NOTIFICATION - HVH COCLER LEAK

Dear Mr. O'Reilly:

In accordance with Plant Technical Specification, 6.9.2.a.3, the following event is reported.

At 2230 hours on September 28, 1983, a service water leak was discovered on Containment Fan Cooler HVH-2. At 2244 hours, the HVH-2 leak was isolated. The NRC was notified of this Unusual Event and of its termination via the Emergency Notification System (ENS) at 2244 hours. In accordance with Technical Specification 3.3.2.2.a, operability testing of the containment spray pumps was completed at 0230 hours. This event is considered a degradation of a containment boundary pursuant to IE Bulletin 80-24 and is reported as such.

This event was reported to Mr. G. P. Beatty, Jr., Manager - Robinson Nuclear Project Department, on September 28, 1983, and to NRC Region II on September 29, 1983.

Very truly yours,

R. E. Morgan

General Manager H. B. Robinson SEG Plant

CLW: CWC/bss

cc: G. P. Beatty, Jr.

S. P. Weise

8310070308 830929 PDR ADOCK 05000261 OFFICIAL COPY!

IE 22

1/0