



Commonwealth Edison
One First National Plaza, Chicago, Illinois
Address Reply to: Post Office Box 767
Chicago, Illinois 60690

DMB

October 4, 1983

Mr. James G. Keppler, Regional Administrator
- Region III
U.S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

Subject: Quad Cities Station Unit 2
Response to IE Bulletin No. 83-03 Action Item 5
NRC Docket No. 50-265

- References (a): IE Bulletin No. 83-03 - R. C. DeYoung letter to
All OLs and CPs dated March 10, 1983
- (b): P. L. Barnes to J. G. Keppler letter dated
June 7, 1983 (PLB 83-62)

Dear Mr. Keppler:

Reference (a) Action Item 5 requested that the Commonwealth Edison Company provide, within ninety (90) days of completion of Action Item 3, a written report of inspection results.

We have completed Action Item 3 for Quad Cities Unit 2. The Unit 1/2 Diesel Generator Cooling Water Pump (DGCWP) discharge check valve 1-3999-85 was inspected during a maintenance outage on September 16, 1983. The valve was found free to swing to the fully open and fully closed positions. The valve was not replaced. The DGCWP was tested for operability prior to unit startup.

To the best of my knowledge and belief the statements contained in the Attachment are true and correct. In some respects these statements are not based on my personal knowledge but upon information furnished by other Commonwealth Edison employees, consultants, and contractor. Such information has been reviewed in

8310120061 831004
PDR ADOCK 05000265
Q PDR

OCT 5 1983

TEH
||

accordance with Company practice and I believe it to be reliable.

Please address any questions that you or your staff may have concerning our response to IE Bulletin No. 83-03 to this office.

Respectfully,

P. L. Barnes

P. L. Barnes
Nuclear Licensing Administrator

cc: US NRC, Document Control Desk
Washington, DC 20555

RIII Inspector - QC

SUBSCRIBED and SWORN to
before me this 4th day
of October, 1983

Rosalee A. Puenta
Notary Public