



**INDIANA & MICHIGAN ELECTRIC COMPANY**

DONALD C. COOK NUCLEAR PLANT  
P.O. Box 458, Bridgman, Michigan 49106  
(616) 465-5901

September 27, 1983

Mr. J.G. Keppler, Regional Administrator  
United States Nuclear Regulatory Commission  
Region III  
799 Roosevelt Road  
Glen Ellyn, IL 60137


Operating License DPR-74  
Docket No. 50-316

Dear Mr. Keppler:

This is to confirm a report made by our Assistant Plant Manager, Mr. B.A. Svensson, to Mr. E.R. Swanson, Senior Resident Inspector at the Donald C. Cook Nuclear Plant at 1850 hours on September 26, 1983. At this time Mr. Swanson was advised that the CO<sub>2</sub> System for the Unit 2 Diesel Generator Room was left in an isolated condition for approximately 2 hours with no personnel in the Diesel Room. Upon discovery, this system was immediately returned to an operable status.

As required by Technical Specification 6.9.1.12, a followup report will be submitted within 14 days.

Sincerely,

  
W.G. Smith, Jr.  
Plant Manager

/bab

cc: John E. Dolan  
M.P. Alexich  
R.F. Kroeger  
H. Brugger  
E.R. Swanson/N.E. DuBry, RO:III  
R.C. Callen, MPSC  
G. Charnoff, Esq.  
J.M. Hennigan  
R.O. Bruggee, EPRI  
INPO  
PNSRC  
J.F. Stietzel  
E.L. Townley  
Dir., IE (40 copies)  
Dir., MIPC (4 copies)

8310120193 830927  
PDR ADDCK 05000316  
S PDR

SEP 30 1983

IE22 1/0