

CONTROL BLOCK: ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)0 1 A L J M F 1 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

CONT

0 1 REPORT SOURCE L 6 0 5 0 0 0 3 4 8 7 0 9 1 3 8 3 8 1 0 0 4 8 3 9
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 At 0015 on 9/13/83, during performance of FNP-1-STP-201.1 (Pressurizer Level

0 3 QIB31LT0459 Calibration and Functional Test), the instrumentation channel as-

0 4 sociated with level transmitter LT-459 (Pressurizer Level - Narrow Range) was

0 5 declared inoperable when it was determined to be out of tolerance. Tech. Spec.

0 6 3.3.1, in part, requires this channel to be operable. Tech. Spec. 3.3.1 action

0 7 statement requirements were met. Health/safety of the public was not affected.

0 8

0 9 SYSTEM CODE I A 11 CAUSE CODE E 12 CAUSE SUBCODE G 13 COMPONENT CODE I N S T R U 14 COMP. SUBCODE Y 15 VALVE SUBCODE Z 16

17 LER/RO REPORT NUMBER 8 3 21 22 23 24 25 26 27 28 29 30 31 32

18 ACTION TAKEN A 18 33 19 FUTURE ACTION Z 19 34 20 EFFECT ON PLANT Z 20 35 21 SHUTDOWN METHOD Z 21 36 22 HOURS 0 0 0 0 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

23 OCCURRENCE CODE 0 3 24 25 26 27 28 29 30 31 32

24 REPORT TYPE L 24 25 26 27 28 29 30 31 32

25 REVISION NO. 0 25 26 27 28 29 30 31 32

26 COMPONENT MANUFACTURER W 1 2 0 26 27 28 29 30 31 32

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 This event was caused by failure of an NLP card. The card was replaced and

1 1 following satisfactory completion of FNP-1-STP-201.1, the LT-459 instrumentation

1 2 channel was declared operable at 0430 on 9/13/83.

1 3

1 4

1 5 FACILITY STATUS E 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

28 % POWER 1 0 0 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

29 OTHER STATUS NA 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

30 METHOD OF DISCOVERY B 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

31 DISCOVERY DESCRIPTION Surveillance Test 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

1 6 ACTIVITY CONTENT RELEASED OF RELEASE Z 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

33 AMOUNT OF ACTIVITY NA 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

34 LOCATION OF RELEASE NA 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

1 7 PERSONNEL EXPOSURES NUMBER 0 0 0 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

37 TYPE Z 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

38 DESCRIPTION NA 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

1 8 PERSONNEL INJURIES NUMBER 0 0 0 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

40 DESCRIPTION NA 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

1 9 LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

42 DESCRIPTION NA 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

2 0 PUBLICITY ISSUED DESCRIPTION N 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

44 DESCRIPTION NA 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

NAME OF PREPARER W. G. Hairston, III

PHONE (205) 899-5156

8310120363 831004
PDR ADCK 05000348
S PDR