




**LOUISIANA** / 142 DELARONDE STREET  
POWER & LIGHT P. O. BOX 6008 NEW ORLEANS, LOUISIANA 70174

February 15, 1984

W3K84-0326  
Q-3-A35.07.57



Mr. John T. Collins  
Regional Administrator, Region IV  
U. S. Nuclear Regulatory Commission  
611 Ryan Plaza Drive, Suite 1000  
Arlington, Texas 76012

REFERENCE: LP&L letter W3K83-1549 dated October 13, 1983

Dear Mr. Collins:

SUBJECT: Waterford SES Unit No. 3  
Docket No. 50-382  
Significant Construction Deficiency No. 57  
"Inadequate Instrumentation and Control Installations and Turnover  
Documentation"  
Seventh Interim Report

The above referenced letter indicated submittal of the Final Report to the  
USNRC on February 15, 1984.

At the present time, final review of corrective action documentation is  
ongoing and is expected to be completed on March 30, 1984. The Final Report  
will be submitted to the USNRC on April 6, 1984.

Very truly yours,

T. F. Gerrets  
Corporate Quality Assurance Manager

TFG:CNH:JC

cc: Director  
Office of Inspection & Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, D.C. 20555

Director  
Office of Management  
Information and Program Control  
U. S. Nuclear Regulatory Commission  
Washington, D.C. 20555

8402280292 840215  
PDR ADOCK 05000382  
S PDR

IE-2710

Mr. John T. Collins  
February 15, 1984  
W3K84-0326  
Page 2

cc: Mr. E. L. Blake  
Shaw, Pittman, Potts, & Trowbridge  
1800 M Street, N.W.  
Washington, D.C. 20036

Mr. W. M. Stevenson  
Monroe & Lemann  
1424 Whitney Building  
New Orleans, Louisiana 70130