

ENCLOSURE 1

NOTICE OF VIOLATION

Virginia Electric and Power Company
North Anna Unit 2

Docket No. 50-339
License No. NPF-7

The following violation was identified during an inspection conducted on November 28 - December 2, 1983. The Severity Level was assigned in accordance with the NRC Enforcement Policy (10 CFR Part 2, Appendix C).

Technical Specification 6.3.1 requires that written procedures be established implemented and maintained covering activities recommended in Appendix "A" of Regulatory Guide 1.33, Revision 2, February 1978.

Contrary to the above, the two examples below demonstrate that procedures were not followed:

- 1) Boron sampling was not recorded at 15 minute intervals as required by step 4.5 during performance of periodic test procedure 2-PT-94.4, "Isothermal Temperature Coefficient Measurement at Hot Zero Power" on May 28, 1983.
- 2) Rod worth measurement calculations were not recorded on data sheets as required by step 4.17 of periodic test procedure 2-PT-94.5, "Rod and Boron Worth Measurements During Boron Dilution". The procedure was signed off as being completed on June 10, 1983.

This is a Severity Level V Violation (Supplement II).

Pursuant to 10 CFR 2.201, you are required to submit to this office within thirty days of the date of this Notice, a written statement or explanation in reply, including: (1) admission or denial of the alleged violations; (2) the reasons for the violations if admitted; (3) the corrective steps which have been taken and the results achieved; (4) corrective steps which will be taken to avoid further violations; and (5) the date when full compliance will be achieved.

Security or safeguards information should be submitted as an enclosure to facilitate withholding it from public disclosure as required by 10 CFR 2.790(d) or 10 CFR 73.21.

Date: DEC 22 1983

8402280480 840213
PDR ADOCK 05000339
Q PDR