

LICENSEE EVENT REPORT

CONTROL BLOCK: 1

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 NYJAFL 200-0000-000 341111 4 5
 7 8 9 14 15 25 26 57 CAT 58

CON'T

01 L 605000333 7091211813 8110051813 9
 7 8 60 61 65 69 74 75 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

02 During normal operation, while performing the valve lineup for sampling
03 using the Post-Accident Sampling System (PASS), the containment hydro-
04 gen and oxygen sample return line and, thereby, the affected systems
05 were isolated. This violated plant Technical Specification 3.7.A.9
06 which requires continuous monitoring of containment hydrogen and oxygen
07 when the containment integrity is required. There was no effect upon
08 public health or safety even though both redundant systems were isolated.

09 S E 11 R 12 A 13 Z Z Z Z Z Z 14 Q 15 Z 16
 7 8 9 10 11 12 13 14 15 16 17 18 19 20

17 8 3 1 0 4 0 3 L 1 0
 21 22 23 24 25 26 27 28 29 30 31 32

X Z Z 20 Z 21 0 0 0 0 Y 23 N 24 Z 25 Z 9 9 9 9 26
 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

10 The PASS and containment atmospheric monitoring system utilize a common
11 discharge line to the suppression pool. When the PASS is to be used, a
12 Solenoid Operated Valve must be opened to this discharge line. This SOV
13 is interlocked with a SOV in the discharge line which prevents backflow
14 Continuation on attached sheet

15 E 28 0 9 9 29 N/A A 31 Operator observation.
 7 8 9 10 11 12 13 14 15 16 17 18 19 20

16 Z 33 Z 34 NA NA
 7 8 9 10 11 12 13 14 15 16 17 18 19 20

17 0 0 0 37 Z 38 NA
 7 8 9 10 11 12 13 14 15 16 17 18 19 20

18 0 0 0 40 NA
 7 8 9 10 11 12 13 14 15 16 17 18 19 20

19 Z 42 NA
 7 8 9 10 11 12 13 14 15 16 17 18 19 20

20 N 44 NA
 7 8 9 10 11 12 13 14 15 16 17 18 19 20

NAME OF PREPARER Terry Herrmann

PHONE: 342-3840

8310250585 831005
 PDR ADOCK 05000333
 S PDR

11/10/81 7-9/81

POWER AUTHORITY OF THE STATE OF NEW YORK
JAMES A. FITZPATRICK NUCLEAR POWER PLANT

DOCKET NO. 50-333

ATTACHMENT TO LER-040

PAGE 2 of 2

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (continued)

of a potentially highly contaminated sample to the containment atmosphere monitoring panels. To correct the situation as it now exists, a change to the JAF FSAR Technical Specifications has been initiated by the site and is currently in the review cycle. The change would allow isolation of the containment atmospheric monitoring system for sample taking operations or training purposes.

James A. FitzPatrick
Nuclear Power Plant
P.O. Box 41
Lycoming, New York 13093
315 342 3840



Corbin McNeill
Resident Manager

October 5, 1983
JAFF 83-1015

Dr. Thomas E. Murley
Regional Administrator
United States Nuclear Regulatory Commission
Region I
631 Park Avenue
King of Prussia, Pennsylvania 19406

SUBJECT: DOCKET NO. 50-333
LICENSEE EVENT REPORT: 83-040

Dear Dr. Murley:

We have enclosed the subject Licensee Event Report in accordance with Section 6.0 of Technical Specifications and USNRC Regulatory Guide 1.16.

If there are any questions concerning this report, please contact Mr. Robert Baker at (315) 342-3840, extension 261.

Very truly yours,

by dr. R. McNeill
CORBIN A. McNEILL, JR.

CAM:RB:ls
ENCLOSURE

CC: USNRC Document Control Desk (1)
INPO Records Center, Atlanta, Georgia (1)
Internal Power Authority Distribution
NRC Resident Manager
Document Control Center
LER/OR File

IE22
1/1