

LICENSEE EVENT REPORT

CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 MDC CN 1200-000000-000341111145
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

CONT

01 REPORT SOURCE L605000317708298380928839
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 At 2145 during normal operation, the containment (CNMT) atmospheric gas-
03 ous and particulate radiation monitors discharge solenoid valve was found
04 to be damaged venting a portion of the flow to the Auxiliary Building.
05 The radiation monitors sample pump was secured and the CNMT isolation
06 valve was shut rendering the radiation monitors inoperable (T.S.3.4.6.1).
07 The CNMT sump level alarm remained operable throughout the event.
08 Similar events: NONE.

09 SYSTEM CODE M C 11 CAUSE CODE E 12 CAUSE SUBCODE X 13 COMPONENT CODE V A L V O P 14 COMP. SUBCODE E 15 VALVE SUBCODE Z 16
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80
17 LER/RO REPORT NUMBER 83 EVENT YEAR 83 SEQUENTIAL REPORT NO. 045 OCCURRENCE CODE 03 REPORT TYPE L REVISION NO. 0
ACTION TAKEN A 18 FUTURE ACTION X 19 EFFECT ON PLANT Z 20 SHUTDOWN METHOD Z 21 HOURS 0000 ATTACHMENT SUBMITTED N 23 NPSR-4 FORM SUB. N 24 PRIME COMP. SUPPLIER A 25 COMPONENT MANUFACTURER A499

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The cause of the failure of the valve is under investigation. The valve
11 was replaced and the system returned to operation. An update report
12 will be submitted.
13
14

15 FACILITY STATUS E 28 % POWER 00 OTHER STATUS N/A 30 METHOD OF DISCOVERY A 31 DISCOVERY DESCRIPTION Operator Observation 32
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80
16 ACTIVITY CONTENT RELEASED OF RELEASE Z 33 AMOUNT OF ACTIVITY Z 34 N/A 35 LOCATION OF RELEASE N/A 36

17 PERSONNEL EXPOSURES NUMBER 000 TYPE Z 37 DESCRIPTION N/A 39
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

18 PERSONNEL INJURIES NUMBER 000 DESCRIPTION N/A 41
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

19 LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION N/A 43
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

20 PUBLICITY ISSUED N 44 DESCRIPTION N/A 45
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

NAME OF PREPARED M.A. Junge/K. Androsik

PHONE: (301) 269-4969/4986

BALTIMORE GAS AND ELECTRIC COMPANY

P.O. BOX 1475

BALTIMORE, MARYLAND 21203

NUCLEAR POWER DEPARTMENT
CALVERT CLIFFS NUCLEAR POWER PLANT
LUSBY, MARYLAND 20657

September 28, 1983

Dr. Thomas E. Murley
Regional Administrator
U.S. Nuclear Regulatory Commission
Region 1
631 Park Avenue
King of Prussia, PA 19406

Docket No. 50-317
License No. DPR-53

Dear Dr. Murley,

In accordance with Technical Specification 6.9.1.9.b, please find the attached thirty day report for LER 83-45/3L.

Should you have any questions regarding this report, we would be pleased to discuss them with you.

Very truly yours,


L.B. Russell

Plant Superintendent

LBR:RA:jcs

att:

cc: Director, Office of Management Information
and Program Control

Messrs: A.E. Lundvall, Jr.
J.A. Tiernan

IE22
1/1