

ATTEN: Document Control Desk  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555

Re: NRC Inspection Report No. 52-21026-01/95-01

REPLY TO A NOTICE OF VIOLATION

Both violation A and B are admitted to. The reasons for the violations was that in the past such concern was focused on liquid iodine. Past information and recommendations seemed to prevail at our laboratory but this has been corrected since the very same day of the inspection. All multi-dose containers of radioiodine are placed inside the fume hood and the motor started as soon as the first dosage is drawn from said container.

Enclosed please find a copy of the radioiodine fume hood radiation survey which was started on February 15, 1995 and will be continued on an ongoing basis. This survey has been instituted following Mr. Héctor Bermúdez' recommendations during the course of the inspection.

Please advise if there is any additional information we need to submit at this time.

*Ramón E. Defendini* 2/6/95  
Ramón E. Defendini  
Administrator  
Regional Memorial Hospital  
Cao Box 859  
Humacao, Puerto Rico 00661

c.c. Regional Administrator, Region II  
Chief, Nuclear Materials Inspection Section, Region II

9503160049 950206  
PDR ADDCK 03019679  
C PDR

LE07  
1/1

*Lealtad a Dios/Servicio a la Humanidad  
Ayer, Hoy y Siempre*



CALL BOX 859  
HUMACAO, PUERTO RICO  
00792  
TELEFONO 852-0768

MODEL: 190-210  
MONTH: February 95

Note: MR/Hr at location

HOSPITAL RYDER MEMORIAL, INC.

*Lealtad a Dios/Servicio a la Humanidad  
Ayer, Hoy y Siempre*



CALL BOX 859  
HUMACAO, PUERTO RICO 00792

U.S. NUCLEAR REGULATORY COMMISSION  
WASHINGTON, D.C. 20555

ATTN: DOCUMENT CONTROL DESK

