

DUKE POWER COMPANY

P.O. BOX 33189
CHARLOTTE, N.C. 28242

HAL B. TUCKER
VICE PRESIDENT
NUCLEAR PRODUCTION

TELEPHONE
(704) 373-4531

83 OCT 21 4:11:36
October 17, 1983


Mr. James P. O'Reilly, Regional Administrator
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, NW, Suite 2900
Atlanta, Georgia 30303

Re: Catawba Nuclear Station
Units 1 and 2
Docket Nos. 50-413 and 50-414 *B*

Dear Mr. O'Reilly:

In the Corrective Action section of Significant Deficiency Report SD 413-414/82-06, dated April 15, 1982, it was stated that all necessary corrective actions would be complete by April 1, 1983. Please be advised that all work required on Unit 1 is complete. Due to the discovery of an incomplete list of affected socket welds, the Unit 2 work has not yet been completed. A complete and accurate list has now been compiled and the required work on Unit 2 socket welds will be completed by February 1, 1985.

Very truly yours,



Hal B. Tucker

RWO/php

cc: Director
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Mr. P. K. Van Doorn
NRC Resident Inspector
Catawba Nuclear Station

Palmetto Alliance
2135½ Devine Street
Columbia, South Carolina 29205

INPO Records Center
Suite 1500
1100 Circle 75 Parkway
Atlanta, Georgia 30339

Mr. Robert Guild, Esq.
Attorney-at-Law
P. O. Box 12097
Charleston, South Carolina 29412

8310270482 831017
PDR ADOCK 05000413
S PDR

OFFICIAL COPY

FE 22
IE27 1/0