




**LOUISIANA**

POWER & LIGHT/Waterford 3 SES/P. O. Box B/Killona, LA 70066

October 14, 1983

W3K83-1568  
Q-3-A35.07.82

Mr. John T. Collins  
Regional Administrator, Region IV  
U. S. Nuclear Regulatory Commission  
611 Ryan Plaza Drive, Suite 1000  
Arlington, Texas 76012



REFERENCE: LP&L letter W3I83-0284 dated August 16, 1983

Dear Mr. Collins:

SUBJECT: Waterford SES Unit No. 3  
Docket No. 50-382  
Significant Construction Deficiency No. 82  
"Bent Control Element Assembly Rods"  
Third Interim Report

The above referenced letter indicated submittal of a Final Report to the USNRC on or before October 14, 1983.

The 16 CEA's returned to Combustion Engineering have been evaluated, reworked and returned to Waterford SES Unit No. 3. These CEA's are scheduled to be receipt inspected and stored in fuel assemblies during the week of October 17, 1983. The applicable discrepancy notice will be closed upon satisfactory receipt inspection.

Following storage of the above CEA's, all full length, 5 finger CEA's will be reinspected and drag tested by LP&L and witnessed by Combustion Engineering. Discrepancy Notice No. 1089-83 (against all CEA's) will be closed upon a satisfactory final acceptance inspection, to be performed by LP&L and CE inspectors.

A Final Report will be submitted to the USNRC on January 15, 1984.

Very truly yours,

*T. F. Gerrets*  
T. F. Gerrets  
Quality Assurance Manager

TFG:CNH:JC

831031 0292 831014  
PDR ALDCK 05000382  
S FDR

110  
IE-27

Mr. John T. Collins  
October 14, 1983  
W3K83-1568  
Page 2

cc: Director  
Office of Inspection & Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, D.C. 20555

Director  
Office of Management  
Information and Program Control  
U. S. Nuclear Regulatory Commission  
Washington, D.C. 20555

Mr. E. L. Blake  
Shaw, Pittman, Potts, & Trowbridge  
1800 M Street, N.W.  
Washington, D.C. 20036

Mr. W. M. Stevenson  
Monroe & Lemann  
1424 Whitney Building  
New Orleans, Louisiana 70130