

ERRATA FOR

INSPECTION REPORT NO. 50-454/83-32 DATED 9/29/83

INTEGRATED DESIGN INSPECTION - BYRON STATION UNIT 1

Page 1-2
Section 1.3
First paragraph

The licensee for Marble Hill is Public Service Company of Indiana rather than Northern Indiana Public Service Company.

Page 1-2
Section 1.3
Second paragraph

Substitute Public Service Company of Indiana for Northern Indiana Public Service Company.

Page 1-2
Section 1.3
Second paragraph

Strike the last sentence which incorrectly states that separate responses for other units will not be required.

Page 1-6
Second full paragraph
Sixth sentence

The sentence should state that a change in support locations "may lead" to a substantial increase rather than stating that it "led" to a substantial increase.