

December 14, 1970

Mr. James C. Malaro:
Isotopes Branch
Division of Materials Licensing
Atomic Energy Commission
Washington, D. C. 20545


Dear Mr. Malaro:

Our customers have been experiencing difficulty obtaining a license from agreement states to possess and operate our model 2-6195 electron capture detector. The heart of the problem is the model number and vender of the nickel-63 foil which changed as indicated in my letter to you dated May 4, 1970.

In talking with a Mr. Silver, N. Y. State Dept. of Labor, in regard to one of these licensing problems, he thought that your office should have informed the agreement states by means of the "Official Catalog Sheet." If this is the usual routine, I would appreciate your taking care of this if it has not already been done. In the meantime, I have written the agreement states of the model number change.

Please call me if you should need additional information.


Sincerely,



M. B. Whittier
Radiation Safety Officer

MBW:ob

Telecon w/ Whittier 1/18/71. Told him
cat. sheet issued 12/29/70. Says he has
problem w/ Tenn. Told him Tenn. should
have sheet in 7-10 days.



COPIES

SENT TO COMPLIANCE