RC Form 591				U.S. NUCLEAR RE	GULATORY COMMISSION
CFR 2.201		SAFETY	INSPECTION		
LICENSEE			2 REGIONAL OFFICE		
Farmingt 1101 Wes	ton Community Hos st Liberty ton, Missouri 63		FEGION ILI OFFICE OF INS 799 ROOSEVEL	PECTION AND 1 ROAD	
DOCKET NUMBER	(S)	4. LICENSE NUMBER		5. DATE OF INSPE	
030-1134	41	24-16616-0	1	December	15, 1983
censee:					
 Within the scope The inspector als those actions at it During this inspe THIS IS A NOTIONAL A	e of this inspection, no viola so verified the steps you has this time. ection certain of your activi	ations were observed. we taken to correct the vio ities, as checked below, we ch is required to be posted		last inspection. We have the second s	
Cfrequencies. D. Records of10 CFR	10 CFR		License Co	ondition Number	e not performed at the prop vere not properly maintaine
E. Documents v	were not properly posted or	r otherwise made available	e. 10 CFR 19.11.		
F. Reports or n	otifications of				were not made in accordan
with 10 CFR	1		or License Condition Nu	mber	
TTH. Lie	censee failed to	record daily co	onstancy tests ov	er a range of	photon
			Ref. License Co		
<u> </u>					
П			and the second s		
L		•			1.000
		•			
		•			
Ц	8312290339 NMS LIC30 24-16616-01	831215 PDR			
	24-16616-01 thin 30 days the actions des	PDR cribed by me to the inspe	ctor will be taken to correct		
	24-16616-01 thin 30 days the actions des	PDR cribed by me to the inspe	ctor will be taken to correct ments of 10 CFR 2.201. No		

*

à

100

¢

1