

50-219
50-220
50-410
50-237

RE: ARC STRIKES - CRITICAL REACTOR COMPONENTS

Numerous arc strikes were detected on pressure vessel nozzles and important piping at Oyster Creek, Nine Mile Point, and Dresden 2 during late stages of construction--many of these were detected by Compliance. It is requested that you review this safety problem at power reactor facilities under construction and verify that an adequate program exists for repairing arc strikes prior to attachment of insulation.

- R. T. Carlson, CO:I
- N. C. Moseley, CO:I
- F. J. Long, CO:II
- G. Fiorelli, CO:III
- H. D. Thornburg, CO:III
- J. W. Flora, CO:IV
- G. S. Spencer, CO:V

8304070493 690425
PDR ADOCK 05000219
G PDR

Original signed by
J. P. O'Reilly

OFFICE ▶	CO <i>JK</i>	CO <i>JPO</i>	J. P. O'Reilly, CO:HQ	4/11/69
SURNAME ▶	JGKeppler:mlc	JPO'Reilly		
DATE ▶	4/11/69	4/11/69		