Roger S. Boyd, Assistant Director for Reactor Projects Division of Reactor Licensing

October 27, 1967

J. P. O'Reilly, Chief, Reactor Inspection and Enforcement Branch Division of Compliance

JERSEY CENTRAL POWER AND LIGHT COMPANY (DOCKET NO. 50-219) CRACK IN STUB TUBE WELD, PRESSURE VESSEL

The attached memorandum is forwarded for information. Our Region I Office (New York) reports that the applicant is conducting an active investigation and that the scope of the problem should be defined by Monday, October 30, 1967.

We are finalizing our plans for an inspector, in company with our consultant, Mr. J. Chyle, to visit the site on October 31, 1967, to review and to evaluate the status of this significant problem.

Attachment: Memo dtd 10/27/67 fm G. Reinmuth, CO, to L. Kornblith, Jr., CO

cc: R. L. Tedesco, DRL,w/att
N. Moseley, CO:I, w/att
G. Reinmuth, CO:HQ, w/o att

PDR ADOCK	PD	
A		1 101

OFFICE .	co//~	
	JPO'Reilly:ej	
SURNAME F	10/27/67	And a second secon
DATE > Form AEC-318 (Rev.)	⊢53) U.S.G	SOVERNMENT PRINTING OFFICE : 1966-O-214-629