

Dean L Quamme Site Manager Midland Project

Midland Project PO Box 1963, Midland, MI 48640 + (517) 631-8650

February 23, 1984

Mr J J Harrison Chief, Midland Section Region III Nuclear Regulatory Commission 799 Koosevelt Road Glen Ellyn, IL 60137

MIDLAND ENERGY CENTER GWO 7020 NCR'S FROM THE FCR/FCN REVIEW FOR SWO'S File: 0505.2 UFI: 03*05*06 Serial: CSC-7367 0460.3 73*10*03 99*04 0250

Per your request, attached is a summary of the NCR's identified as a result of the recent FCR/FCN review.

DLQ/DDJ/klp

cc: JEKarr, CIO RAWells, MPQAD BHPeck, MEC NIReichel, MEC RJCook, NRC Site

A

Distribution (See below)

FROM DATaggart, Midland

DATE February 21, 1984

To

CC

SUBJECT MIDLAND ENERGY CENTER PROJECT - IDENTIFIED NCR'S FROM THE FCR/FCN REVIEW FOR SWO'S Consumers Power Company

DAT-21-84

KJGill, Midland PDMilano, Midland BMPalmer, Midland

Attached for your information please find a summary of the NCR's which were identified as a result of the recent FCR/FCN review. Should you have any specific questions regarding these items please feel free to contact Pat Milano.

Jaggant

DISTRIBUTION:

RAWells, Midland DLQuamme, Midland HPLeonard, Midland JKMeisenheimer, Midland WRBird, P-14-418A JLWood, Midland GEParker, Midland RCSember, Midland NReichal, Midland DPerry, Midland

NCRs From FCR/FCN Review For SWOs

	NCR#	Discipline	Nonconformance
1.	C-00913	Mechanical	Penetrations drilled and rebar cut in isolation valve pit wall and Turbine Building wall w/o prior Project appro- val, as required by Spec C-231.
2.	C-00024	I&C	Contrary to note on Drawing J-3150(Q) Instrument Support, 2LT-3976BB2, 10- cated 4" east of required location. Tolerance was only ±2".
3.	C-00933	Electrical	Wire number change to blue conductor of cable OBB6601B proposed by FCN E-5298. FCN was not clearly dis- approved by Project Engineering and thus, the disapproved change was incorporated into Drawing E-900. E-900 calls for wire tag now to be "6". Drawing E-37 identifies wire number as "5G1".
4.	C-00934 (Replaced by NCR	Electrical C-01012	FCN E-5744 revised sizes of terminal boxes 2J1109 and 2J1110 from 30"x20"x8" to 30"x30"x8". However, FCN not attached to Drawing E-46 at time of installation and thus, wrong box size could be installed. NCR C-01012 written on the same problem which superceded this NCR.
5.	C+00935	Electrical	Drawing E-791 provides dimensional plans for raceway supports. E-748 provides dimension sections for raceway supports. FCR E-639 was not incorporated into Drawings E-748(Q), Sheets 1 & 2. Dimensions on E-741(Q) do not agree with E-748(Q) sht 1. Proposed connection details on FCR- E-639 for E748, Sh. 2, were disapproved Status of supports indeterminate.
6	H_00133_27	Civil (HVAC)	FCR C-3638 written against detail 7/C 902 at one specific location. The FCR was dispositioned to be a revision for all locations. However, the FCR was not attached to Drawing C-902.

	NCR	Discipline	Nonconformance
7.	H-00134-22	Civil (HVAC)	Same as H=00133-ZZ but for different hanger.
8.	H-00135-22	Civil (HVAC)	Same as H=00133-ZZ but for different hanger.
9.	H-00175-ZZ	Civil (HVAC)	FCN C924 never incorporated into Drawing C-953(Q) as so stated in disposition.
10.	H-00176-ZZ	Civil (HVAC)	FCN C-878 never incorporated into Drawing C-935(Q) as so stated in disposition.