


LOUISIANA
POWER & LIGHT

142 DELARONDE STREET
P O. BOX 6008 • NEW ORLEANS, LOUISIANA 70174 • (504) 366-2345

April 27, 1984

W3K84-0980
Q-3-A35.07.103

Mr. John T. Collins
Regional Administrator, Region IV
U. S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76012



REFERENCE: LP&L Letter W3K84-0631 dated March 16, 1984

Dear Mr. Collins:

SUBJECT: Waterford SES Unit No. 3
Docket No. 50-382
Significant Construction Deficiency No. 103
"Radflex Wall Penetrations"
Second Interim Report

The above referenced letter indicated submittal of the Final Report to the USNRC on April 30, 1984.

At the present time, approximately 9 penetrations (RB3) remain to be inspected/repared in the Fuel Handling Building, this is scheduled to be completed in early May 1984.

The Final Report will be submitted to the USNRC on May 15, 1984.

Very truly yours,

T. F. Gerrets
Corporate Quality Assurance Manager

TFG:CNH:SSTG

cc: Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

Director
Office of Management
Information and Program Control
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

8405080038 840427
PDR ADOCK 05000382
S PDR

IL 27/10

Mr. John T. Collins

April 27, 1984
W3K84-0980

Page 2

cc: Mr. E. L. Blake
Shaw, Pittman, Potts & Trowbridge
1800 M Street, N.W.
Washington, D.C. 20036

Mr. W. M. Stevenson
Monroe & Lemann
1424 Whitney Building
New Orleans, Louisiana 70130

Mr. W. A. Cross
7910 Woodmont Avenue
Suite 1200
Bethesda, Maryland 20814