H. Denton L. Beratan RE: DRS ALTERNATIVE INSPECTION AND TEST PROGRAMS -TURKEY POINT DOME REPAIR

> Maccary dropped these off on his way to Oregon and will not be available for the next several days. I understand they are the latest revisions of the DRS alternative inspection and test programs for the Turkey Point dom repair. You will note that the number of tendons to be removed in alternative 2 has not yet been determined. I believe we should discuss the revised alternatives before the meeting with the applicant.

Enclosure: DRS - Proposed Inspection See www atd 2/17/7/ and Test Programs -RNET JRO'R Turkey Point

R. H. Engelken

2/17/71

8305190165 710319 PDR ADDCK 05000250

OFFICE >	,CO		q
SURNAME >	RHEngelken		
DATE >	2/17/71		
Evem APC-318 (Rev	9.59)	II S GOVERNMENT PRINTING OFFICE 1969 - O. 364-509	