

SEP 25 1970

R. S. Boyd, Assistant Director for Boiling Water Reactors, DRL
R. C. DeYoung, Assistant Director for Pressurized Water Reactors, DRL

CURRENT STATUS OF TURKEY POINT #3 CONTAINMENT DOME INVESTIGATION

Since the licensee has no clues concerning the failure mechanism of the concrete dome at Turkey Point 3, we wish to note that we have general reservations relating to the adequacy of the Point Beach, Palisades, Oconee, and Calvert Cliffs containment buildings. We currently feel that further inspections are desirable; however, the depth and direction of such inspections must await the results of analyses being conducted by Florida Power and Light, and Bechtel at Turkey Point 3. If you do not agree, or if you desire additional information or action by Compliance on a more urgent basis, please let me know.

R. H. Engelken, Assistant Director
for Inspection and Enforcement
Division of Compliance

cc: P. A. Morris, DRL
L. D. Low, CO
A. Giambusso, CO
D. Muller, DRL
R. Ireland, DRL
C. Long, DRL
H. Denton, CO

B305190325 710319
PDR ADOCK 05000250
A PDR

OFFICE ▶	CO <i>DRH</i>	CO <i>RHE</i>				
SURNAME ▶	MH:reth:ee JPO'Reid JPO	RHenge				
DATE ▶	9/23/70	10/4/70				