

Docket Nos. 50-250
and 50-251

NOV 19 1968

Distribution:
AEC Doc. Room
Formal
Suppl. (2)
DRL Reading
RPB-3 Reading
Orig: PSCheck
FW Karas
RS Boyd
CG Long
OGC, TB Conner

Florida Power & Light Company
P. O. Box 3100
Miami, Florida 33101

Attention: Mr. George Kinsman
Senior Vice President

Gentlemen:

We have reviewed the report on honeycombing in the Turkey Point Unit 3 containment mat furnished under your letter of August 13, 1968. We have also reviewed the supplement to this report dated October 25, 1968. *not in file*

We are satisfied that you have determined the extent of the honeycombing and that you have performed an adequate investigation into the causes of the problem. Further, we find that the repair procedures and post-repair inspections you propose are sound.

Therefore, we have no objection to your proceeding with the repair program as outlined in the above referenced documents.

IS/OR 12/4/68
FR
JLX
LX
AD
BMR

Sincerely,

Original Signed by
Peter A. Morris

Peter A. Morris, Director
Division of Reactor Licensing

cc: Mr. Roy B. Snapp
1725 K Street, NW
Washington, DC 20006

8 3587

8305200174 700209
PDR ADOCK 05000250
A PDR

COPY SENT REGION *AL*

DEC 3 1968

RPB-3/DRL	RPB-3/DRL	RP/DRL	DRL
PSCheck:pt	CGLong	RSBoyd	PAMorris
11- -68	11- -68	11- -68	11- -68