



Commonwealth Edison
Quad-Cities Nuclear Power Station
Post Office Box 216
Cordova, Illinois 61242
Telephone 309/654-2241

D. Jensen

NJK-76-166

April 30, 1976

J. Keppler, Regional Director
Office of Inspection and Enforcement
Region III
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Reference: Quad-Cities Nuclear Power Station
Docket No. 50-254, DPR-29, Unit 1
Appendix A, Sections 3.7.D.1, 6.6.B.2.b

Enclosed please find Reportable Occurrence Report No. 50-254/76-17 for Quad-Cities Nuclear Power Station.

This report is submitted to you in accordance with the requirements of Technical Specification 6.6.B.2.

Very truly yours,

COMMONWEALTH EDISON COMPANY
QUAD-CITIES NUCLEAR POWER STATION

N. J. Kalivianakis

N. J. Kalivianakis
Station Superintendent

NJK/lk

cc: G. A. Abrell

8306130105 760527
PDR ADOCK 05000254
S PDR

184

MAY

COPY SENT REGION III

CENSEE EVENT REPORT

CONTROL BLOCK: 1 6

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE NAME 01 I L Q A D I	LICENSE NUMBER 0 0 - 0 0 0 0 0 - 0 0	LICENSE TYPE 4 1 1 1 1 1	EVENT TYPE 0 3
CATEGORY 01 CONT	REPORT TYPE L	REPORT SOURCE L	DOCKET NUMBER 0 5 0 - 0 2 5 4
EVENT DATE 0 4 0 2 7 6	REPORT DATE 0 4 3 0 7 6		

EVENT DESCRIPTION

02	While performing monthly MSIV surveillance, dual indication was received for	80
03	valves A0 1-203-1B and A0 1-203-1D. Upon investigation, both valves were found	80
04	to be closed. A minor air leak was also discovered on the A0 1-203-1D valve	80
05	operator assembly. (RO 50-254/76-17)	80
06		80

SYSTEM CODE 07 C D	CAUSE CODE E	COMPONENT CODE V A L V 0 P	PRIME COMPONENT SUPPLIER N	COMPONENT MANUFACTURER N O I 5	VIOLATION Y
---	---	---	---	---	--

CAUSE DESCRIPTION

08	(Proximate Cause: Equipment Malfunction) The open limit switches on A0 1-203-1B and	80
09	A0 1-203-1D were found to be out of alignment. The minor air leak in the valve opera-	80
10	tor was corrected by the installation of a new seal "E" ring (manufactured by	80

FACILITY STATUS 11 G	% POWER 0 0 0	OTHER STATUS NA	METHOD OF DISCOVERY B	DISCOVERY DESCRIPTION Surveillance Test
FORM OF ACTIVITY RELEASED 12 Z	CONTENT OF RELEASE Z	AMOUNT OF ACTIVITY NA	LOCATION OF RELEASE NA	

PERSONNEL EXPOSURES

NUMBER 13 0 0 0	TYPE Z	DESCRIPTION NA
--	---	-------------------

PERSONNEL INJURIES

NUMBER 14 0 0 0	DESCRIPTION NA
--	-------------------

OFFSITE CONSEQUENCES

15	NA
--	----

LOSS OR DAMAGE TO FACILITY

TYPE 16 Z	DESCRIPTION NA
--	-------------------

PUBLICITY

17	NA
--	----

ADDITIONAL FACTORS

18	(Cause Description continued) Miller Fluid Division Pt. #052-PS007-2000)	80
--	--	----

19		80
--	--	----

NAME: L. L. Henson

PHONE: 309-654-2241 Ext. 247