



UNITED STATES  
ATOMIC ENERGY COMMISSION  
WASHINGTON, D.C. 20545

FEB 23 1974

B. Grier

Action - please  
check with "L"  
and coordinate  
any action.

20112  
FEB 23 1974  
Stephen H. Hanauer, Director, DRTA  
John F. O'Leary, Director, L  
Donald F. Knuth, Director, RO  
Lester Rogers, Director, RS

CRACKS IN FEEDWATER SPARGERS IN THE KKM NUCLEAR STATION, GE-BWR

The enclosed letter from the Swiss regulatory office  
(F. Weehuizen) describes experience they are having with feedwater  
spargers in their BWR at Muhleberg, and requests our advice on  
this matter. This information may be interesting and useful to  
you. I would appreciate your giving it your early attention and  
sending me your recommendations, for advice to the Swiss, by  
March 8, 1974.

16011  
20112  
Clifford K. Beck, Director  
Office of Government Liaison -  
Regulation

Enclosure:  
Ltr Weehuizen to Beck dtd 2/20/74

8307090241 730308  
PDR ADOCK 05000245  
P PDR