

May 27, 1970

NOTE TO DR. MANN

CAROLINA POWER AND LIGHT COMPANY (ROBINSON 2)
FAILURE OF SAFETY VALVE NOZZLE

Attached are copies of two very recent reports which contain the information you requested on May 25.

I have been informed that the pressurizer heaters were automatically turned off when the pressurizer water reached a level of ~12 percent. As a precautionary measure, the heaters were also manually turned off by the operators.

Please return the reports to me when you are finished with them. Also, please let me know if you need any additional information.

R. H. Engelken

Enclosures:

1. CO Rpt No. 50-261/70-5
w/memo of 5/13/70
2. Trip Rpt dtd 5/14/70

cc w/o encl:

J. P. O'Reilly, CO
F. Nolan, CO

8311180057 700922
PDR ADOCK 05000261
PDR

50-261 Incident

OFFICE ▶	CO <i>FAV</i>					
SURNAME ▶	RHEngelken:ej					
DATE ▶	5/27/70					