ILLINOIS POWER

Docket No. 50-461

Document Control Desk Nuclear Regulatory Commission Washington, D.C. 20555

Subject:

Clinton Power Station - Unit 1

Licensee Event Report No. 90-003-01

Dear Sir:

Enclosed is Licensee Event Report No. 90-003-01: 13 Resemount Transmitters
Inoperable due to Loose Housing Covers and a Broken Neck Seal. The report has been revised to update the information provided, including the licensee contact, corrective action and maintenance work document numbers, additional root cause investigation results, and corrective action changes. Minor editorial changes have also been made. This report is being submitted in accordance with the requirements of 10CFR50.73.

Sincerely yours,

J. G. Cook
Vice President

RSF/csm

Enclosure

cc: NRC Clinton Licensing Project Manager

NRC Resident Office, V-690

Regional Administrator, Region III, USNRC

Illinois Department of Nuclear Safety

INPO Records Center

190040

9507190156 950713 PDR ADDCK 05000461 S PDR JE27

Illinois Power Company Clinton Power Station P.O. Box 678 Clinton, IL 61727 Tel 217 935-5623 Fax 217 935-4632

L45-95(07-13)LP

10CFR50.73

John G. Cook Vice President U-602467

> 2C.220 JGC-288-95 July 13, 1995