

Vepco

1 and 2

VIRGINIA ELECTRIC AND POWER COMPANY

Surry Power Station
P.O. Box 315
Surry, Virginia 23883

December 31, 1974

Director of Regulatory Operations
230 Peachtree
Suite 818
Atlanta, Georgia 30303

This is to inform you by telecopy within twenty-four (24) hours of an Abnormal Occurrence that was noted on December 30, 1974, at Surry Nuclear Power Station.

A crack was found in the body of a Unit 2 containment spray check valve. Subsequent investigation has revealed rockshaft cracks in five other containment spray and recirculation spray check valves. The Unit 2 containment spray check valve and all cracked rockshafts are being replaced.

E. M. Sweeney, Jr.
E. M. Sweeney, Jr.
Station Manager

8403010485 750113
PDR ADCK 05000280
S PDR