

*official*

DEC 30 1991

Docket No. 50-261  
License No. DPR-23

Carolina Power and Light Company  
ATTN: Mr. Lynn W. Eury  
Executive Vice President  
Power Supply  
P. O. Box 1551  
Raleigh, NC 27602

Gentlemen:

SUBJECT: NRC INSPECTION REPORT NO. 50-261/91-25

This refers to the inspection conducted by R. P. Carrion of this office on November 18-22, 1991. The inspection included a review of activities authorized for your H. B. E. Inson facility. At the conclusion of the inspection, the findings were discussed with those members of your staff identified in the report.

Areas examined during the inspection are identified in the report. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observation of activities in progress.

The enclosed Inspection Report identifies activities that appeared to violate NRC requirements that are not cited; therefore, a response is not required.

We are concerned about this because of failure of the package to meet shipping requirements.

In accordance with 10 CFR 2.790(a), a copy of this letter and its enclosure will be placed in the NRC Public Document Room.

Should you have any questions concerning this letter, please contact us.

Sincerely,

*/s/*

William E. Cline, Chief  
Radiological Protection and  
Emergency Preparedness Branch  
Division of Radiation Safety  
and Safeguards

Enclosure:  
NRC Inspection Report

cc w/encl: (Cont'd on page 2)

9201170079 911230  
PDR ADOCK 05000261  
PDR

*IEO1*