

GPU Nuclear Corporation

Post Office Box 388 Route 9 South Forked River, New Jersey 08731-0388 609 971-4000 Writer's Direct Dial Number:

March 14, 1984

Mr. D. M. Crutchfield, Chief Operating Reactors Branch No. 5 Division of Licensing U.S. Nuclear Regulatory Commission Washington, DC 20555

Dear Mr. Crutchfield:

Subject: Oyster Creek Nuclear Generating Station

Docket No. 50-219 IE Bulletin No. 80-11

Masonry Wall Failure Consequence Analysis

The enclosed reports provide the subject analysis. These evaluations were incorporated by reference (References 5 and 7) in our correspondence to you dated November 2, 1983. They were prepared for GPU Nuclear by the Impell Corporation.

If you should have ay questions, please contact Mr. Paul Czaya at (609)971-4893.

Very truly yours,

Peter B. Fiedler

Vice President and Director

Oyster Creek

PBF:PFC:dam Enclosures

cc: Dr. Thomas E. Murley, Administrator Region I U.S. Nuclear Regulatory Commission 631 Park Avenue King of Prussia, PA 19406

NRC Resident Inspector (w/o enclosures) Oyster Creek Nuclear Generating Station Forked River, NJ 08731

8403200056 840314 PDR ADOCK 05000219 Q PDR IEII Add The

