DISTBIBUTION: Central Files LB #4 r/f DHood EAdensam MDuncan

NOTE TU: Frank Rinaldi, Structural Engineering Branch Dwane Boyd, IE, Region III

FROM: Darl Hood Licensing Branch #4, DL

SUBJECT: 50.55(e) REPORTS TO BE INCLUDED IN MIDLAND SUILS HEARING

P.UG 2 6 1981

During the Midland Soils hearing on August 11, 1981, the Board declined to consider several 50.55(e) reports which intervenor Stamiris wanted discussed. However, in doing so, the Board noted that three of these 50.55(e) reports were relevant to seismic matters and should be discussed in later sessions of the instant hearing. The three reports discuss:

- 1. Auxiliary Building Seismic Analysis (81-02)
- 2. HSSS Setsmic plus LOCA Reanalysis (80-07)
- 3. Component Cooling Water Design (either 80-06 or 90-01)

Recent updates of these reports are enclosed.

SUR

Although not included in the above discussions, the 50-55(e) report on the BMST foundation is also relevant to the hearing and will be included in the hearing session on that fix. Also, the report on NSSS seismic plus LOCA is linked somewhat to another 50.55(e) report (79-10) on reactor vessel broken anchor bolts in that the revised analysis is based upon the modified vessel support scheme.

Pr. J. Thessin of OELD will be discussing with you shortly how these matters should be incorporated into Staff testimony or otherwise sponsored at the hearing.

& Ron Hernan Darl Bood, Project Hanager Bicensing Branch #4 Division of Licensing

cc:	 W. Paton, w/o encl. J. Keppler, w/o encl. R. Cook, IE Resident Inspective J. Kane, w/encl. F. Schauer, w/o encl. E. Brown, w/encl. J. Thessin, w/encl. H. Jensen, w/encl. G. Mazetis, w/o encl. 	1 ctor, w/o encl.	~ /	
	R. Hernan, w/encl.	DL:LB#4 Ru	8 0/ALB#4	i i i i i i i i i i i i i i i i i i i
8107080070 XA 9		DHood:eb	EAdensam	
		8/20/81	8/1/ /81	