Southern California Edison Company



P. O. BOX 800

2244 WALNUT GROVE AVENUE

ROSEMEAD, CALIFORNIA 91770

February 22, 1973

TELEPHONE 213-572-2292

Directorate of Licensing U. S. Atomic Energy Commission Washington, D. C. 20545

Attention: Mr. Donald J. Skovholt

Assistant Director for Operating Reactors

Gentlemen:

ACK B. MOORE

VICE PRESIDENT

Subject: Docket No. 50-206

San Onofre Nuclear Generating Station

Unit 1

In accordance with your request of December 22, 1972, we have reviewed the control circuits for circuit breakers of safety related equipment at San Onofre Nuclear Generating Station Unit 1.

Based on our review, it is concluded that disabling of one component does not, through incorporation in other interlocking or sequencing controls, render redundant components inoperable. All modes of test, operation, and failure were considered.

We are also reviewing station procedures to assure whenever part of a redundant system is removed from service, the portion remaining in service is functionally tested immediately after disabling of the affected portion and, if possible, before disabling of the affected portion. This review, along with any necessary revisions to the procedures, will be completed by April 30, 1973.

Sincerely,

. Angrico

COPY SENT REGION

42/90 H-WR VTK

> 8302220621 731025 PDR ADDCK 05000206 Q PDR