

LICENSEE EVENT REPORT

CONTROL BLOCK:

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE NAME: G1 N J O C P 1 1

LICENSE NUMBER: 0 0 - 0 0 0 0 0 - 0 0

LICENSE TYPE: 4 1 1 1 0

EVENT TYPE: 0 1

CATEGORY: 0 1 CONT

REPORT TYPE: M I

REPORT SOURCE: T

DOCKET NUMBER: 0 5 0 - 0 2 1 9

EVENT DATE: 1 2 2 3 7 5

REPORT DATE: 0 1 0 2 7

EVENT DESCRIPTION

02 Vacuum breaker V-26-7 failed to demonstrate operability during surveillance testing. Excessive force had to be applied to effect valve movement. V-26-7 was seated prior to surveillance test. V-26-7 was secured closed immediately after problem was identified. Since closed initially, valve would have performed its function during pipe break accidents. Minimal significance since one inoperative valve reduces vacuum relief area by 7% and only ~25% of available capacity is required for negative pressure protection. V-26-7 will be repaired and returned to service during the current 1975/1976 refueling outage. (Reportable occurrence 50-219/75/34/1P).

SYSTEM CODE: S A

CAUSE CODE: E

COMPONENT CODE: X X X X X X

PRIME COMPONENT SUPPLIER: N

COMPONENT MANUFACTURER: A 5 8 5

VIOLATION: N

CAUSE DESCRIPTION

08 Valve V-26-7 is an Atwood & Morrill Company check valve with 1.75 square feet of vent area. An apparent "growing" problem has been experienced with the teflon bushings. This has been discussed with General Electric and Atwood & Morrill Co. A purchase order for replacement parts has been issued.

STATUS: E

% POWER: 0 8 0

OTHER STATUS: NA

METHOD OF DISCOVERY: B

DISCOVERY DESCRIPTION: Routine surveillance test

FORM OF ACTIVITY RELEASED: Z

CONTENT OF RELEASE: Z

AMOUNT OF ACTIVITY: NA

LOCATION OF RELEASE: NA

PERSONNEL EXPOSURES

NUMBER: 0 0 0

TYPE: Z

DESCRIPTION: NA

PERSONNEL INJURIES

NUMBER: 0 0 0

DESCRIPTION: NA

OFFSITE CONSEQUENCES

13 NA

LOSS OR DAMAGE TO FACILITY

TYPE: Z

DESCRIPTION: NA

PUBLICITY

17 NA

ADDITIONAL FACTORS

18 NA


19 *Donald Ross* *Phone 201-539-6111*

8302230080 760102
PDR ADOCK 05000219
S PDR

Jersey Central Power & Light Company



MADISON AVENUE AT PUNCH BOWL ROAD • MORRISTOWN, N. J. 07960 • 201-539-6111

MEMBER OF THE
General  Public Utilities Corporation

January 2, 1976
GN-76-001

IE FILE COPY

Mr. R. Boyd, Acting Director
Division of Reactor Licensing
Office of Nuclear Reactor Regulation
United States Nuclear Regulatory Commission
Washington, DC 20555



Dear Mr. Boyd:

Subject: Oyster Creek Station
Docket No. 50-219
Licensee Event Report --
Reportable Occurrence No. 50-219/75/34/1P

This letter forwards the attached Licensee Event Report to report Reportable Occurrence No. 50-219/75/34/1P in compliance with paragraph 6.6.2.a of the Technical Specifications.

Very truly yours,

Donald A. Ross, Manager
Generating Stations-Nuclear

CS
Enclosures

cc: Mr. J. P. O'Reilly, Director
Office of Inspection and Enforcement, Region 1

COPY SENT REGION 