

# LICENSEE EVENT REPORT

CONTROL BLOCK:

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE NAME														LICENSE NUMBER										LICENSE TYPE					EVENT TYPE	
01	N	Y	N	M	P	1									4	1	1	1	1	0	1									
7	8	9				14	15								25	26				30	31	32								

CATEGORY		REPORT TYPE	REPORT SOURCE	DOCKET NUMBER					EVENT DATE					REPORT DATE										
01	CONT	M	I	L	L	0	5	0	0	2	2	0	0	7	2	5	7	5	0	8	0	4	7	5
7	8	57	58	59	60	61						68	69					74	75					80

**EVENT DESCRIPTION**

02	Environmental Technical Specifications requires an Environmental Sample (Milk Sample)																				80
03	be collected and analysed within 8 days of collection. Analysis was not completed																				80
04	until 9 days following collection.																				80
05																					80
06	AOR 75-20																				80

SYSTEM CODE		CAUSE CODE	COMPONENT CODE					PRIME COMPONENT SUPPLIER	COMPONENT MANUFACTURER				VIOLATION		
07	Z	Z	d	Z	Z	Z	Z	Z	Z	Z	9	9	9	N	
7	8	9	10	11	12				17	43	44			47	48

**CAUSE DESCRIPTION**

08	The sample was sent to the lab via ground transportation. In the future, it will																				80
09	be sent by air. Eberline Corporation contacted and told of speed requirements.																				80
10																					80

FACILITY STATUS		% POWER	OTHER STATUS					METHOD OF DISCOVERY		DISCOVERY DESCRIPTION					
11	E	0	8	0					a	Review by Supervisor					
7	8	9	10	12	13				44	45				46	80

FORM OF ACTIVITY RELEASED		CONTENT OF RELEASE	AMOUNT OF ACTIVITY					LOCATION OF RELEASE						
12	Z	Z	N/A											
7	8	9	10	11					44	45				80

**PERSONNEL EXPOSURE**

NUMBER		TYPE	DESCRIPTION		
13	0	0	0	2	N/A
7	8	9	11	12	13

**PERSONNEL INJURIES**

NUMBER		DESCRIPTION		
14	0	0	0	N/A
7	8	9	11	12

**ADVERSE CONSEQUENCES** Probable

15	None																				80
----	------	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

**LOSS OR DAMAGE TO FACILITY**

TYPE		DESCRIPTION	
16	2	N/A	
7	8	9	10

PUBLICITY  
None  
8303110276 750804  
PDR ADOCK 05000220  
S PDR


**ADDITIONAL FACTORS**

18	The results of the analysis indicated I-131 well below limits.																				80
19																					80

NAME: T.J. Dente

PHONE: (315) 343-2110

NIAGARA MOHAWK POWER CORPORATION

NIAGARA  MOHAWK

300 ERIE BOULEVARD, WEST  
SYRACUSE, N. Y. 13202

August 4, 1975



Mr. James P. O'Reilly  
Directorate of Regulatory Operations  
Region I  
United States Nuclear Regulatory Commission  
631 Park Avenue  
King of Prussia, Pa. 19406

RE: Docket No. 50-220

Dear Mr. O'Reilly:

In accordance with Nine Mile Point Nuclear Station Unit #1 Technical Specification 6.9, we hereby submit Licensee Event Reports 75-18 thru 75-20 which document the Abnormal Occurrences for July 1975.

These reports conform to the requirements of Regulatory Guide 1.16, Revision 2 and were completed within the intent of the Licensee Event Report Instruction Booklet 00E-SS-001, dated October, 1974, revised December 24, 1974. Due to the minimal significance category of the reports, no supplemental report is included.

Very truly yours,

R.R. Schneider  
Vice President  
Electric Operations

TJD/mm

Enc. 3 copies

cc: K.R. Goller (30 copies)

COPY SENT REGION 

8639