

LICENSEE EVENT REPORT

CONTROL BLOCK:

--	--	--	--	--	--

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE NAME:

01	I	L	D	R	S	2
----	---	---	---	---	---	---

 LICENSE NUMBER:

00	-	00	00	00	-	00
----	---	----	----	----	---	----

 LICENSE TYPE:

4	1	1	1	1
---	---	---	---	---

 EVENT TYPE:

03

CATEGORY:

01	CONT
----	------

 REPORT TYPE:

L

 REPORT SOURCE:

L

 DOCKET NUMBER:

050	-	0237
-----	---	------

 EVENT DATE:

0	2	0	7	7	6
---	---	---	---	---	---

 REPORT DATE:

0	2	1	7	7	6
---	---	---	---	---	---

EVENT DESCRIPTION

02 DURING ROUTINE SURVEILLANCE TESTING, THE DRYWELL HIGH PRESSURE SCRAM
03 SENSOR PS-2-1621-B WAS FOUND TO BE SET 0.07 PSI BEYOND THE
04 TECHNICAL SPECIFICATION LIMIT OF 2.00 PSI. THE REMAINING THREE SENSORS
05 OF THE "1 OUT OF 2, TWICE" LOGIC WERE OPERABLE; THEREFORE THE R.P.S.
06 SYSTEM WAS OPERABLE. THE SENSOR WAS IMMEDIATELY RECALIBRATED. (CONTINUED)

SYSTEM CODE:

I	A
---	---

 CAUSE CODE:

E

 COMPONENT CODE:

I	N	S	T	R	U
---	---	---	---	---	---

 PRIME COMPONENT SUPPLIER:

N

 COMPONENT MANUFACTURER:

S	3	8	2
---	---	---	---

 VIOLATION:

Y

CAUSE DESCRIPTION

08 SETPOINT DRIFT
09 RANGE 2-6 PSI; MAX. PRESS. 200 PSI; SERIAL NO. 62 2 861
10

FACILITY STATUS:

E

 % POWER:

0	9	5
---	---	---

 OTHER STATUS:

NA

 METHOD OF DISCOVERY:

B

 DISCOVERY DESCRIPTION:

NA

FORM OF ACTIVITY RELEASED:

Z

 CONTENT OF RELEASE:

Z

 AMOUNT OF ACTIVITY:

NA

 LOCATION OF RELEASE:

NA

PERSONNEL EXPOSURES

NUMBER:

0	0	0
---	---	---

 TYPE:

Z

 DESCRIPTION:

NA

PERSONNEL INJURIES

NUMBER:

0	0	0
---	---	---

 DESCRIPTION:

NA

OFFSITE CONSEQUENCES

15

NA

LOSS OR DAMAGE TO FACILITY

TYPE:

Z

 DESCRIPTION:

NA

PUBLICITY

17

NA

B303310530 760217
PDR ADCK 05000237
S PDR

ADDITIONAL FACTORS

18 EVENT DESCRIPTION (CONT.) THIS IS THE FIRST TIME SETPOINT DRIFT BEYOND

19 TECH SPEC. LIMITS HAS OCCURRED ON THESE SENSORS. (050-237/76-4)

NAME: G. REIMERS PHONE: EXT 265