

DEC 19 1983

Docket No. : 030-13337
License No.: 53-17797-01
Control No.: 70021

Kuakini Medical Center
347 N. Kuakini Street
Honolulu, Hawaii 96817

Gentlemen:

This is in reference to your application dated August 25, 1983 and your letter dated December 7, 1983 to renew your byproduct material license.

The Procedures and Certification Branch of the U.S.N.R.C., Washington D.C., 20555 [(301) 427-4240] has not received information regarding increasing the maximum activity of iodine-125 to be used in AECL Model C-235 sources. Also, no information has been received which would describe the custom designed bone mineral analyzer. We cannot approve the use of the 800 millicurie iodine-125 source or continued use of the bone mineral analyzer until the increase in source activity and use of the device have been reviewed and approved.

We will complete the review of your renewal request upon receipt of this information. You should submit your response within thirty (30) days from the date of this notice. Please reply in duplicate, and refer to Mail Control No. 70021.

Sincerely,

Printed signed by
Beth A. Riedlinger

Beth A. Riedlinger
Health Physicist (Licensing)
Materials Radiation Protection
Inspection and Licensing Section

840719C466 840621
NMS LIC30
53-17797-01 PDR

| | | | | | | |
|---------|---------------|--|--|--|--|--|
| OFFICE | RV <i>BR</i> | | | | | |
| SURNAME | Riedlinger:fr | | | | | |
| DATE | 12/19/83 | | | | | |