Warnick UNITED STATES NUCLEAR REGULATORY COMMISSION REGION III 799 ROOSEVELT ROAD GLEN ELLYN, ILLINOIS 60137 October 8, 1975 H. D. Thornburg, Chief, Field Coordination and Enforcement Branch Office of Inspection and Enforcement, Headquarters COMMONWEALTH EDISON COMPANY (DRESDEN UNIT 2) DOCKET NO. 50-237 PRELIMINARY NOTIFICATION OF EVENT OR UNUSUAL OCCURRENCE CRACK IN CONTAINMENT INERTING LINE The attached communication covering the preliminary information regarding the crack in containment inerting line at Dresden Unit 2 is forwarded with the recommendation it be issued as a "Preliminary Notification." Reactor Operations Branch Attachment: As stated cc w/attachment: J. G. Davis, DD R. F. Warnick, Regional Coordinator B. H. Grier, IE:HQ 303310702 751008 I&E -III-75-046 PDR