

Duke Power Company
P.O. Box 1007
Charlotte, NC 28201-1007

Hai B. Tucker
Senior Vice President
Nuclear
(704) 373-4331



DUKE POWER

March 6, 1992

U. S. Nuclear Regulatory Commission
ATT: Document Control Desk
Washington, DC 10555

Subject: McGuire Nuclear Station, Unit 1
Docket No. 50-369
Inservice Inspection
1991 Refueling Outage 7

Attached is controlled copy No.5 of the Inservice Inspection Report which summarizes inservice inspection results for the subject refueling outage. This report is being submitted in accordance with the ASME Code Section XI.

Any questions may be directed to Laura T. Burba at 704 373-2365.

Very truly yours,

A handwritten signature in cursive script, appearing to read 'H. B. Tucker'.

H. B. Tucker

LTB/

XC: W/O Attachment

S. D. Ebnetter
Regional Administrator, Region II

W. T. Orders
Senior Resident Inspector

R. E. Martin, ONRR

A047
11

9203120111 920306
PDR ADOCK 05000369
Q PDR