




LOUISIANA

POWER & LIGHT/Waterford 3 SES/P. O. Box B/Killona, LA 70066

October 13, 1983

W3K83-1549
Q-3-A35.07.57

Mr. John T. Collins
Regional Administrator, Region IV
U. S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76012



REFERENCE: LP&L letter W3183-0254 dated July 29, 1983

Dear Mr. Collins:

SUBJECT: Waterford SES Unit No. 3
Docket No. 50-382
Significant Construction Deficiency No. 57
"Inadequate Instrumentation & Control Installations & Turnover
Documentation"
Sixth Interim Report

The above referenced letter indicated submittal of a Final Report to the USNRC no later than October 14, 1983.

At the present time, review of the final documentation indicates remaining corrective action. This additional corrective action is scheduled to be completed by January 24, 1984. A Final Report will be submitted to the USNRC by February 15, 1984.

Very truly yours,

A handwritten signature in cursive script, appearing to read 'T. F. Gerrets'.

T. F. Gerrets
Quality Assurance Manager

TFG:CNH:VBR

cc: Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

8310280012 831013
PDR ADOCK 05000382
S PDR

110
IE-27

Mr. John T. Collins
October 13, 1983

W3K83-1549

Page 2

cc: Director
Office of Management
Information and Program Control
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

Mr. E. L. Blake
Shaw, Pittman, Potts, & Trowbridge
1800 M Street, N.W.
Washington, D.C. 20036

Mr. W. M. Stevenson
Monroe & Lemann
1424 Whitney Building
New Orleans, Louisiana 70130