

DmB

ILLINOIS POWER COMPANY



1605-L  
U-10155

CLINTON POWER STATION, P.O. BOX 678, CLINTON, ILLINOIS 61727  
May 16, 1984

Docket No. 50-461

Mr. James G. Keppler  
Regional Administrator  
Region III  
U.S. Nuclear Regulatory Commission  
799 Roosevelt Road  
Glen Ellyn, Illinois 60137

Subject: Potential Deficiency 55-82-09  
10CFR50.55(e)  
Small Bore/Instrumentation Piping, and Conduit  
Support Design Calculations

Dear Mr. Keppler:

In Illinois Power Company letter dated January 12, 1984 (ref: letter D.P. Hall to J.G. Keppler, U-10117), your office was provided an interim report addressing the status of the subject 10CFR50.55(e) investigation. It was anticipated at the time that approximately ninety (90) days would be necessary to complete the investigation and to provide a final report on the issue.

Illinois Power Company is presently involved in the final actions necessary to evaluate the adequacy of the investigation and the corrective actions taken. It is anticipated that approximately thirty (30) additional days will be necessary to complete and evaluate the results of this activity, and to provide a final report on the issue.

If you have any questions or comments regarding the status of actions taken on this issue, please contact Illinois Power Company.

Sincerely,

D. P. Hall  
Vice President

RDW/lag

cc: NRC Resident Office  
Director - Office of I&E, US NRC, Washington, DC 20555  
Illinois Department of Nuclear Safety  
INPO Records Center

8405220093 840516  
PDR ADOCK 05000461  
S PDR

IE27  
MAY 1/0

MAY 18 1984