

APPENDIX A

Notice of Violation

Baltimore Gas and Electric Company
Calvert Cliffs Nuclear Power Plant

Docket/License Nos. 50-317; DPR-53
50-318; DPR-69

During an NRC inspection conducted on January 5, 1992, through February 15, 1992, and in accordance with the NRC Enforcement Policy (10 CFR Part 2, Appendix C), the following violation was identified.

Technical Specification 6.8.1.a requires that written procedures shall be established, implemented, and maintained covering the applicable procedures recommended in Appendix A of Regulatory Guide 1.33, Revision 2, February 1978. Regulatory Guide 1.33 requires administrative procedures for access to containment and operating instructions to maintain containment integrity.

Contrary to the above, on December 24, 1991, no procedures existed for the operation of the Unit 1 emergency air lock door. This contributed to the improper operation of the air lock and resultant loss of Unit 1 containment integrity.

This is a Severity Level IV violation (Supplement I).

Pursuant to the provisions of 10 CFR 2.201, Baltimore Gas and Electric Company is hereby required to submit a written statement or explanation to the U.S. Nuclear Regulatory Commission, ATTN: Document Control Desk, Washington, D.C. 20555, with a copy to the Regional Administrator, Region I, and a copy to the NRC Resident Inspector, within 30 days of the date of the letter transmitting this Notice of Violation (Notice). This reply should be clearly marked as a "Reply to a Notice of Violation" and should include for each violation: (1) the reason for the violation, or, if contested, the basis for disputing the violation, (2) the corrective steps that have been taken and the results achieved, (3) the corrective steps that will be taken to avoid further violations, and (4) the date when full compliance will be achieved. Where good cause is shown, consideration will be given to extending the response time.

OFFICIAL RECORD COPY

a:CIR92-02.CC