



UNITED STATES  
ATOMIC ENERGY COMMISSION  
WASHINGTON, D.C. 20545

UNITED STATES  
ATOMIC ENERGY COMMISSION  
Division of Compliance  
REGION III  
799 Roosevelt Road  
Glen Ellyn, Illinois 60137

July 15, 1970

J. P. O'Reilly, Chief, Reactor Inspection and Enforcement Branch  
Division of Compliance, Headquarters

NORTHERN STATES POWER COMPANY (MONTICELLO)  
DOCKET NO. 50-263

The attached report of an inspection of the subject facility by the assigned inspector on May 25, 26, 27, and 28, 1970, is forwarded for information. No items of nonconformance were noted.

One item of safety significance was noted in connection with the unsafe failure of a number of relays discovered during safety system functional testing. This matter was the subject of a Region III Inquiry Memorandum dated June 2, 1970.

Northern States Power has been requested to submit a report of this matter to DRL, based on its safety significance.

Several DDR matters were resolved, and the safe end repair and replacement program was followed up.

*Harold D. Thornburg*  
Harold D. Thornburg  
Senior Reactor Inspector

Attachment:  
CO Rpt No. 263/70-10 by  
C. D. Feierabend dtd 6-23-70  
(2 cys)

cc: E. G. Case, DRS (3)  
P. A. Morris, DRL  
R. S. Boyd, DRL (2)  
R. C. DeYoung, DRL (2)  
D. J. Skovholt, DRL (3)  
P. Howe, DRL (2)  
L. Kornblith, Jr., CO:HQ  
Regional Directors, CO

REG files

9102140409 700715  
PDR ADDCK 05000263  
Q PDR