

NSP

REGULATORY DOCKET FILE COPY

NORTHERN STATES POWER COMPANY

MINNEAPOLIS, MINNESOTA 55401

September 23, 1977

Mr Victor Stello, Director
Division of Operating Reactors
c/o Distribution Services Branch, DDC, ADM
U S Nuclear Regulatory Commission
Washington, DC 20555



Dear Mr Stello:

MONTICELLO NUCLEAR GENERATING PLANT
Docket No. 50-263 License No. DPR-22

Feedwater Nozzle Repair Program Revision

Our August 31, 1977 letter discussed plans to remove cladding from the Monticello feedwater nozzles. We stated that addenda to the ASME Code up to and including the Winter of 1976 Addenda would be used. Title 10 CFR 50.55a does not recognize addenda this recent. We will therefore adhere to the Summer 1975 Addenda of Section XI and the Summer 1976 Addenda of Section III.

The change in addenda affects the way the program is documented but does not result in any physical change in the repair program.

Yours very truly,

L O Mayer, PE
Manager of Nuclear Support Services

LOM/MHV/deh

cc: J G Keppler
G Charnoff
MPCA
Attn: J W Ferman

9105160422 770923
PDR ADDCK 05000263
PDR

772720083

AM 195

U.S. NUCLEAR REGULATORY COMMISSION

DOCKET NUMBER

50-263

FILE NUMBER

NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL

Mr. Victor Stello

FROM:

NSP
Minneapolis Minnesota 55401
L. O. Mayer

DATE OF DOCUMENT

09/23/77

DATE RECEIVED

09/29/77

NUMBER OF COPIES RECEIVED

100

LETTER
☐ ORIGINAL
☒ COPY

☐ NOTORIZED
☒ UNCLASSIFIED

PROP

INPUT FORM

DESCRIPTION

Advising NSP will adhere to the
Summer 1975 Addenda of Section XI and the Summer
1976 Addenda of Section III regarding plans to
remove cladding from the Monticello feedwater
nozzles...

1p

ENCLOSURE

LANT NAME: MONTICELLO

jcm 09/29/77

SAFETY

FOR ACTION/INFORMATION

BRANCH CHIEF: (7)

DAVIS

INTERNAL DISTRIBUTION

REG FILE

I & E (2)

OELD

HANAUER

CHECK

STELLO

EISENHUT

SHAO

BAER

BUTLER

GRIMES

J. COLLINS

EXTERNAL DISTRIBUTION

CONTROL NUMBER

LPDR: MINNEAPOLIS MR.

TIC

NSIC

16 CYS ACRS SENT CATEGORY B

172729083