

NORTHERN OWER COMPAN

MINNEAPOLIS, MINNESOTA BBAD

DOCKETED May 3, 1976 MAY 6 1976 CLEAR REGULA Mr. D L Ziemann, Chief Operating Reactors Branch No. Division of Operating Reactors US Nuclear Regulatory Commission Washington, DC 20555 Regulatory Decket File

Dear Mr Ziemann:

05160430 ADOCK

MONTICELLO NUCLEAR GENERATING PLANT Docket No. 50-263 License No. DPR-22

Revision to Technical Specifications Relating to Hydraulic Snubbers

In your letter dated December 17, 1975 you requested Northern States Power Company to submit a License Amendment Request to modify the Technical Specifications covering safety related hydraulic snubbers. The modifications we were requested to submit included:

- a. Specifying what must be included in visual snubber inspections.
- b. Enlarging the scope of Table TS 3.6.1 to include informe tion on snubber area radiation levels and ease of removal.
- C . Deletion of snubbers in High Radiation Areas or snubbers "especially difficult to remove" from functional testing.

Item (C) has presented some difficulty. We have completed an initial evaluation of each safety related snubber at Monticello and have found that the majority of the snubbers located in the drywell can be classified as either "especially difficult to remove" or located in areas of greater than 100 mR/hr after shutdown. Snubbers were considered "especially difficult to remove" if:

- HSSA-30 or larger in size. а.
- b. Greater than 5 feet above or greater than 1 foot below an installed platform.

1 4541

Under the provisions of the model Technical Specifications sent to us on December 17, 1975, this would exempt most drywell snubbers from periodic

- 2 -

May 3, 1976

removal for operability testing. We believe that a sampling of these snubbers should be included in those selected for functional testing.

We will continue to conduct snubber surveillance in accordance with the more restrictive Technical Specifications issued on September 15, 1976. During the next drywell snubber inspection, however, we will conduct a detailed radiation survey at the location of each safety related snubber. Following this survey we will submit the Technical Specification Change Request outlined in your December 17, 1975 letter. This submittal will most likely utilize a higher radiation level than 100 mR/hr as the criterion to exempt a snubber from inspection.

Yours very truly,

P. Mayor

L O Mayer, PE Manager, Nuclear Support Services

LOM/DMM/deb

cc: J G Keppler G Charnoff MPCA Attn: J W Ferman

BUTION FOR PA	FURNISHING	STATES IS , MI ER	POWER COMPANY		
LTR CENSE AMENDMEN SPEC. COVERING	FURNISHING	IS , MI TER	INPUT FORM OSURE	5/3/76 DATE RECEIVED 5/6/76 NUMBER OF COPIES RECEIVED ONE SIGNED	
LTR CENSE AMENDMEN SPEC. COVERING	FURNISHING	IS , MI TER	INPUT FORM OSURE	DATE RECEIVED 5/6/76 NUMBER OF COPIES RECEIVED ONE SIGNED	
LTR CENSE AMENDMEN SPEC. COVERING	L. O. MAY PROP FURNISHING NT REQUEST	ER	OSURE ACKNOWLI	5/6/76 NUMBER OF COPIES RECEIVED ONE SIGNED	
LTR CENSE AMENDMEN SPEC. COVERING	FURNISHING NT REQUEST	ENCL	ACKNOWLI	ONE SIGNED	
LTR CENSE AMENDMEN SPEC. COVERING	NT REQUEST	ENCL	ACKNOWLI	DGED	
CENSE AMENDMEN SPEC. COVERING	NT REQUEST	ENCL	ACKNOWLI		
CENSE AMENDMEN SPEC. COVERING	NT REQUEST		ACKNOWLI		
			DO NOT REN	JOVE	
			and all a allo		
	and a local state of the state of the state of		1933	1RO 5/7/76 RJL	
	FOR ACTI	DN/INFO	ASSIGNED AD :	1K0 5/1/10 K51	
	a a secondar a la selectra de la se				
		LCICK CX			
And the second			A REAL PROPERTY AND A REAL		
DI	645		DIG: NOOT. :		
	INTERNA	LDISTR	TOUTION	n de la cara de cara de la construir en la construir de la construir de la construir de la construir de la cons	
C even				ENVIRO TECH	
				ERMST	
the second s				EALLARD	
	VI MICK			SPANGLER	
ENOT	THEFTHE				
the second s				SITE TECH	
		The state of the state of the state	OPERATING REACTORS	GAMMILL	
successful and an international inclusion of the local sectors of the				STEPP	
the design of the local distance of the second				1.ULMAN	
Contraction of the International State of Contraction			OPERATING TECH		
ENT REAC	TOR SAFETY	X	EISENHUT	SITE ANALYSIS	
the second second in the second		X		VOLLMER	
second and the second sec		X	BAER	BUNCH	
and a lost of the barrier of a second state of the		8	SCHMENCER	J. COLLINS	
second and the property like the second second		X		KREGER	
And the second sec					
A TO A	I		SITE SAFETY & E VIE	10	
the second s			ANALYSIS	The second	
and a lot of the second s			DENTON & MULLER		
		ION		CONTROL NUMBER	
			INCOMMAVEN NATL LAI	a state of the second sec	
IS March INATI	V-IE		ULRIESON (ORNL)		
US, MUNN. NATI				4541	
REG.	TIR			1 100 1 1	
LA 1	'DR HILLIANTS				
	RENT REAC NOVA ROSZ CHEC AT & SALJ RUTI	INTERNA SYSTEMS SAFETY HEINEMAN SCHROEDER F ENGINEERING MACCARY KNIGHT SIHWEIL PAWLICKI NENT REACTOR SAFETY ROSS NOVAK ROSS NOVAK ROSZTOCZY CHECK AT & I SALTZMAN RUTBERG	INTERNAL DISTR DIGES INTERNAL DISTR SYSTEMS SAFETY HEINEMAN SCHROEDER F ENGINEERING MACCARY KNIGHT SIHWEIL PAWLICKI NENT REACTOR SAFETY ROSS NOVAK ROSZTOCZY CHECK AT & I SALTZMAN	ZIE MANN PRANCH CHIEF : SMALDER PROJECT MANAGER : DIGGS LIC. ASST. : INTERNAL DISTRIBUTION	