

Docket Nos. 50-263
50-282
and 50-306

APR 7 1977

Northern States Power Company
ATTN: Mr. L. O. Mayer, Manager
Nuclear Support Services
414 Nicollet Mall - 8th Floor
Minneapolis, Minnesota 55401

Gentlemen:

RE: MONTICELLO NUCLEAR GENERATING PLANT
PRAIRIE ISLAND NUCLEAR GENERATING PLANT, UNITS NO. 1 AND 2

In our review of reports submitted by licensees concerning malfunctions of diesel generators, we find that in some cases the information available to the control room operator to indicate the operational status of the diesel generator may be imprecise and could lead to misinterpretation. This can be caused by the sharing of a single annunciator station by alarms that indicate conditions that render a diesel generator unable to respond to an automatic emergency start signal and alarms that only indicate a warning of abnormal, but not disabling, conditions. Another cause can be the use of wording on an annunciator window that does not specifically say that a diesel generator is inoperable (i.e., unable at the time to respond to an automatic emergency start signal) when in fact it is inoperable for that purpose.

We, therefore, request that you review the alarm circuitry and diesel generator control circuitry for the diesel generators at your facilities to determine how each condition that renders a diesel generator unable to respond to an automatic emergency start signal is alarmed in the control room. These conditions include not only the trips that lock out the diesel generator start and require manual reset, but also control switch or mode switch positions that block automatic start, loss of control voltage, insufficient starting air pressure or battery voltage, etc. This review should consider all aspects of possible diesel generator operational conditions, for example test conditions and operation from local control stations. One area of particular concern is the unreset condition following a manual stop at the local station which terminates a diesel generator test prior to resetting the diesel generator controls for enabling subsequent automatic operation.

OFFICER	9105220305 770407			
SURNAME	PDR ADOCK 05000263			
DATE	PDR			

APR 7 1977

Northern States Power Company

Please respond within 45 days of your receipt of this letter by providing the following information:

- (a) all conditions that render the diesel generator incapable of responding to an automatic emergency start signal as discussed above;
- (b) the wording on the annunciator window in the control room that is alarmed for each of the conditions identified in (a);
- (c) any other alarm signals that also cause the same annunciator to alarm;
- (d) any condition that renders the diesel generator incapable of responding to an automatic emergency start signal which is not alarmed in the control room; and
- (e) any proposed modifications resulting from this evaluation.

Sincerely,
Original signed by

Don K. Davis

Don K. Davis, Acting Chief
Operating Reactors Branch #2
Division of Operating Reactors

cc: See next page

DISTRIBUTION:

Docket (3)
 NRC PDR (3)
 Local PDR (1)
 ORB-2 Reading
 DKDavis
 RPSnaider
 MGrotenhuis
 RMDiggs
 DEisenhut
 JMcGough
 Attorney, OELD
 I&E (3)
 JRBuchanan
 TBAbernathy
 ACRS (16)
 TVWambach

OFFICE →	<i>RSnaider</i> DOR:ORB-2	DOR:ORB-2	DOR:ORB-1	DOR:ORB-2		
SURNAME →	RSnaider:esp	MGrotenhuis	TVWambach	DKDavis		
DATE →	4/7/77	4/7/77	4/7/77	4/7/77		

APR 7 1977

cc: Gerald Charnoff, Esquire
Shaw, Pittman, Potts and Trowbridge
1800 M Street, N. W.
Washington, D. C. 20036

Sandra S. Gardebring
Executive Director
Minnesota Pollution Control Agency
1935 W. County Road B2
Roseville, Minnesota 55113

The Environmental Conservation Library
Minneapolis Public Library
300 Nicollet Mall
Minneapolis, Minnesota 55401

Arthur Renquist, Esquire
Vice President - Law
Northern States Power Company
414 Nicollet Mall
Minneapolis, Minnesota 55401

Howard J. Vogel, Esquire
Legal Counsel
2750 Dean Parkway
Minneapolis, Minnesota 55416

Hr. Kenneth Dzigan
Environmental Planning Consultant
Office of City Planner
Grace Building
421 Wabasha Street
St. Paul, Minnesota 55102

Anthony Z. Roisman, Esquire
Roisman, Kessler and Cashden
1025 15th Street, N. W., 5th Floor
Washington, D. C. 20005

OFFICE ➤						
SURNAME ➤						
DATE ➤						