


NSP

NORTHERN STATES POWER COMPANY

MINNEAPOLIS, MINNESOTA 55401

August 3, 1976

Mr D L Ziemann, Chief
Operating Reactors Branch #2
Division of Operating Reactors
U S Nuclear Regulatory Commission
Washington, DC 20555



Dear Mr Ziemann:

MONTICELLO NUCLEAR GENERATING PLANT
Docket No. 50-263 License No. DPR-42

Final Response to March 11, 1975 Letter

Your March 11, 1975 letter requested information associated with Monticello recirculation bypass piping. Our March 24, 1975 and June 24, 1975 letters provided portions of the information requested. Attached is a report entitled, "Failure Analysis of the Type 304 Stainless Steel in Recirculation Bypass Lines of the Monticello BWR Power Plant". This report completes our response to your request.

Yours very truly

L. O. Mayer

L O Mayer, PE
Manager, Nuclear Support Services

LOM/MHV/deb

cc: J G Keppler
G Charnoff
MPCA
Attn: J W Ferman

Attachment

10
[Handwritten signature]

8090

9105220309 760803
PDR ADOCK 05000263
P PDR

50-263

Mr Ziemann

Northern States Pwr Co
Minneapolis, Mn
L O Mayer

8-3-76

8-10-76

one signed

INDEXED
 SERIALIZED
 FILED
 UNCLASIFIED

Ltr re our 3-11-75 & their 3-24-75 & 6-24-75
submittals.....trans the following:

Failure Analysis of the Type 304 Stainless
Steel 4-In Recirculation Bypass Lines of
the Monticello BWR Plant.....

(40 cys encl rec'd)

Monticello

566
RR

8-10-76 ehf

Ziemann (5)
Snider
Diggs

(2)

Minneapolis, Mn

J
8090