

APPENDIX A

Notice of Violation

Duquesne Light Company  
Beaver Valley Power Station

Docket No. 50-412  
License No. NPR-73

As a result of the inspection conducted on June 2 - July 6, 1991, and in accordance with the "General Statement of Policy and Procedure for NRC Enforcement Actions," 10 CFR Part 2, Appendix C (1991), the following violation was identified:

- A. Technical Specification 6.8.1.C requires that written procedures be established, implemented and maintained covering surveillance and test activities of safety related equipment.

Contrary to the above, surveillance procedures were not established to cover operation of both Unit 2 diesel generators with the following safety related components:

- 1) Valve 2EG0-115, strainer 2EGO\*STR24A, and valve 2EG0-117 which constituted the alternate lube oil flow path for the 2-1 EDG.
- 2) Valve 2EG0-114, strainer 2EGO\*STR24B, and valve 2EG0-116 which constituted the alternate lube oil flow path for the 2-2 EDG.

This is a Severity Level IV violation (Supplement I-D).

Pursuant to the provisions of 10 CFR 2.201, Duquesne Light Company is hereby required to submit a written statement or explanation to the U.S. Nuclear Regulatory Commission, ATTN: Document Control Desk, Washington, D.C. 20555 with a copy to the Regional Administrator, Region I, and a copy to the NRC Resident Inspector at the facility that is the subject of the Notice, within 30 days of the date of the letter transmitting this Notice of Violation (Notice). This reply should be clearly marked as a "Reply to a Notice of Violation" and should include for the violation: (1) the reasons for the violation, or, if contested, the basis for disputing the violation, (2) the corrective steps that have been taken and the results achieved, (3) the corrective steps that will be taken to avoid further violations, and (4) the date when full compliance will be achieved. Where good cause is shown, consideration will be given to extending the response time.

OFFICIAL RECORD COPY

a:INR91-14,BV