



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION II
101 MARIETTA STREET, N.W.
ATLANTA, GEORGIA 30303

APR 02 1984

Mississippi Power and Light Company
ATTN: Mr. J. B. Richard
Senior Vice President, Nuclear
P. O. Box 1640
Jackson, MS 39205

Gentlemen:

SUBJECT: REPORT NO. 50-416/83-58


We have received your responses of March 13, 1984, to our Notices of Violation and Deviations, issued on February 9, 1984, concerning activities conducted under NRC Operating License No. NPF-13. Your responses have been evaluated and we have found that your response to violation 83-58-02 is incomplete for the following reasons.

In your response to violation 83-58-02, it is stated that the reason for not fully implementing Technical Specification requirements into plant administrative procedure 01-S-01-11, (Plant Safety Review Committee), was due to improper procedure preparation. Our identification of this violation in its self, is indicative that the procedure was improperly prepared. What is required to be addressed, is how and why this condition existed, as well as what corrective steps you will take in the preparation/review of procedures and associated changes to ensure their compliance with Technical Specifications and other regulatory requirements.

Within 30 days of your receipt of this letter, please provide a supplemental response to violation 83-58-02 which addresses those requirements expressed above.

Should you have any questions concerning this letter, we will be glad to discuss them with you.

Sincerely,


David M. Verrelli, Chief
Project Branch 1
Division of Project and
Resident Programs

cc: J. E. Cross, Plant Manager
Ralph T. Lally, Manager of Quality
Middle South Services, Inc.

8405300425 840515
PDR ADOCK 05000416
Q PDR