



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION II
101 MARIETTA STREET, N.W.
ATLANTA, GEORGIA 30303

MAY 02 1984

Report Nos. 50-338/84-11, 50-339/84-11, 50-280/84-14 and 50-281/84-14

Licensee: Virginia Electric and Power Company

Docket Nos.: 50-338, 50-339, 50-280 and 50-281

License Nos.: NPF-4, NPF-7, DPR-32 and DPR-37

Facility Name: North Anna Units 1 and 2; Surry Units 1 and 2

Approved by: H. C. Dance 4/30/84
H. C. Dance, Chief, Branch 2, Division of Date Signed
Reactor Projects

SUMMARY

An enforcement conference was held in the Region II Office on April 17, 1984, at 1:00 p.m. Mr. James P. O'Reilly opened the meeting and then Mr. J. H. Ferguson, Mr. W. L. Stewart, Mr. W. R. Cartwright, Mr. E. W. Harrell, and Mr. J. L. Wilson presented Virginia Electric and Power Company's description of several items of concern that were identified during recent NRC inspections at the North Anna and Surry facilities.

The details of the NRC findings will be described in NRC Reports 50-338/84-06, 50-339/84-06, 50-280/84-10, 50-281/84-10, 50-280/84-11 and 50-281/84-11.

The issues listed below were discussed for safety significance and corrective actions to prevent recurrence.

- Surry Snubber Inspection Program

The establishment of snubber service life as required by Technical Specifications was not fully implemented.

- North Anna and Surry Reactor Vessel Head Vents

The functional operability of the head vents was delayed due to misinterpretation of the 10 CFR 50.44 rule requirements. This resulted in manual isolation valves being closed and procedural and training requirement delays.

- Quality Assurance Program

QA involvement in plant and corporate activities should have prevented these occurrences.

- Reactor Trip Breaker Maintenance

Timely incorporation of vendor recommendations in breaker maintenance procedures will be further reviewed.

MAY 02 1984

2

The NRC expressed concern that corporate and facility management controls failed to identify these events that should have caused VEPCO to take corrective actions. VEPCO stated that their intent is to operate in absolute compliance with requirements.

Attachment:
Meeting Attendance; April 17, 1984

MAY 02 1984

ATTACHMENT

MEETING ATTENDANCE

APRIL 17, 1984

VIRGINIA ELECTRIC AND POWER COMPANY (VEPCO) REPRESENTATIVES

J. H. Ferguson - Executive Vice President/Chief Operating Officer
J. I. Oatts - Senior Vice President-Power Operations
W. L. Stewart - Vice President-Nuclear Operations
J. W. Waddill - Executive Manager-Quality Assurance
W. R. Cartwright - Manager-Nuclear Operations Support
J. L. Wilson - Station Manager-Nuclear (Surry)
E. W. Harrell - Station Manager-Nuclear (North Anna)
M. R. Kansler - Superintendent-Technical Services (Surry)
R. F. Driscoll - Manager-Quality Assurance (Surry)
S. B. Eisenhart - Licensing Coordinator (North Anna)
C. M. Robinson, Jr. - Manager-Civil Engineering

Nuclear Regulatory Commission

J. P. O'Reilly, Regional Administrator
H. C. Dance, Chief, Projects Branch 2, DRP
S. A. Elrod, Chief, Projects Section 2C, DRP
C. M. Upright, Chief, Quality Assurance Programs Section, DRS
H. E. P. Krug, Acting Chief, Operations Programs Section, DRS
M. W. Branch, Senior Resident Inspector, DRP
D. J. Burke, Senior Resident Inspector, DRP
M. J. Davis, Resident Inspector, DRP
G. M. Nejfelt, Enforcement Specialist
J. M. Puckett, Enforcement Specialist
B. W. Jones, Regional Counsel
H. L. Whitener, Reactor Inspector, DRS
J. J. Lenahan, Reactor Inspector, DRS
J. R. Miller, Chief ORB #3, NRR
J. D. Neighbors, Project Manager-Surry, NRR