

APPENDIX A

NOTICE OF VIOLATION

Niagara Mohawk Power Corporation  
Nine Mile Point, Unit 2

Docket No. 50-410  
License No. CPPR-112

As a result of the inspection conducted on March 5 - April 7, 1984 and in accordance with the NRC Enforcement Policy (10 CFR 2, Appendix C) published in the Federal Register on March 8, 1984 (49 FR 8583), the following violation was identified:

10 CFR 50, Appendix B, Criterion III and the Nine Mile Point, Unit 2 PSAR require that applicable regulatory requirements and design basis are correctly translated into specifications and drawings. Regulatory Guide 1.29 compliance requires that non-safety items be designed such that their potential seismic failure will not impair the operability of safety related components.

Contrary to the above, on August 5, 1983 and February 15, 1984, the licensee was informed of two conditions involving control room partition walls and a crane over the emergency diesel generator which were designed as non-seismic items. The potential seismic failure of the forementioned items could have detrimental effects upon plant safety related components.

This is a Severity Level IV Violation (Supplement II).

Pursuant to the provisions of 10 CFR 2.201, Niagara Mohawk Power Corporation is hereby required to submit to this office within 30 days of the date of the letter transmitting this Notice, a written statement or explanation in reply, including: (1) the corrective steps which have been taken and the results achieved; (2) the corrective steps which will be taken to avoid further violations; and (3) the date when full compliance will be achieved. Where good cause is shown, consideration will be given to extending the response time.